

Vehicle Engineering Series



MORRIS COOPER S

2nd Edition Corrections.

Last update 6/2/2024

Page 14. The block is drilled 0.330" and threaded 3/8" 18TPI through for the Helicoil.

Page 85. Carburettor angle is 30°.

Page 108. Table 7.1.4 3rd Gear Overall Ratio should be 1.353

Page 118. Table 7.3.1 3rd Gear Overall Ratio should be 1.353

Page 178. Brake Master Cylinder Lockheed Part No. is 4222/922.

Page 265. Catch material is brass.

Page 292. Heater control cable AYG9297, new heater fitted Dec 1970.

Page 288. A PVC strip 24A1276 41 5/8" long is fitted along the seat pan flange.