

# Vehicle Engineering Series



## MORRIS·MINI·MOKE

### **1<sup>st</sup> Edition Corrections**

**Last update 2/9/2022**

Page 13. YJBAB6R is referred to as both Morris Mini Moke and BMC Moke in company documents. The model name is BMC Moke.

Page 49. Water pump AYG234 introduced 2/YDO18 in 1970, not AYA219.

Page 86. Fuel supply lines shown for saloon in error. Revised pictures below.

Page 110. Locally produced primary gears only used on Moke 9YB/U/H 1464 onwards.

Page 147. Straight groove in steering rack introduced in the Mini range 1971. Pinion introduced 1967 has same overall length but protrudes a lesser amount above the boss in the housing.

Page 197, 198. Should be Engine No. 6708

Page 296. Engine code 9YH|We|H should be 9YH|U|H 3 speed synchromesh

Coated steel Bundy tube ¼" AYK2085 OD supplies fuel from the tank to flexible hose AYA2055 11.5" long, and then AYK2086 flexible hose to pump.




Fig. 5.1.9 Fuel supply pipes AYK2085.




Fig. 5.1.10 Fuel supply pipe AYK2086.